This Page Is Inserted by IFW Operations and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

As rescanning documents will not correct images, please do not report the images to the Image Problem Mailbox.





Figure 1

FIGURE 2 – Try-on Garment (200)









Figure 3

X Axis Motor (74a) Top Head Unit (72a) Scan Table (76) FIGURE 4A -- Scanner System (10) **Ball Screw** Front Cover

Processor- Based System (22) Y Axis Motor (74b) Main Controller Box Slide Cover Bottom Head Unit (72b) Compressor Hole Air Holes (88)







(29) OUIT YIEW




Figure 6






Figure 7B








Figure 8B




Figure 9






Figure 11A




Figure 11B




Figure 12A





Figure 12B







Figure 13



A. Original